



TDK Corporation

## HHM2910E1

Gawo la Nambala:  
 Wopanga / Chinthu:  
 Mafotokozedwe Akatundu  
 Datasheets:  
 Mkhaliidwe wa RoHS  
 Zolemba  
 Chombo Chochokera  
 Njira Yoperekerana

HHM2910E1  
 TDK Corporation  
 RF DIR COUPLER 1.71GHZ-2.03GHZ  
[HHM2910E1.pdf](#)  
 Kutsogolera / RoHS Kumvera  
 300204 pcs stock  
 Hong Kong  
 DHL/Fedex/TNT/UPS/EMS

**PEMPHO LA QUOTATION**

Chithunzi chingakhale choyimira. Onani ndondomeko zogwiritsira ntchito mankhwala.

### Mafofotokozedwe a HHM2910E1

GAWO LA NAMBALA	HHM2910E1
WOPANGA	TDK Corporation
KUFOTOKOZERA	RF DIR COUPLER 1.71GHZ-2.03GHZ
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Kutsogolera / RoHS Kumvera
CHIWERENGERO CHIPEZEKA	300204 pcs
TSAMBA LAZAMBIRI	<a href="#">HHM2910E1.pdf</a>
MNDANDANDA	HHM
BWERERANI KUTAYIKA	-
MPHAMVU - MAX	-
KUPAKA	Original-Reel®
PHUKUSI / MLANDUWU	0402 (1005 Metric), 4 PC Pad
MAINA ENA	445-172643-6
MPHUNO YOPANDA CHISOKONEZO (MSL)	1 (Unlimited)
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Lead free / RoHS Compliant
KUSUNGULUMWA	34dB
KULOWETSA KULOWA	0.25dB
KUSINTHASINTHA	1.71GHz ~ 2.03GHz
KUFOTOKOZEDWA KWAMBIRI	RF Directional Coupler 1.71GHz ~ 2.03GHz 21.2 ± 1dB 0402 (1005 Metric), 4 PC Pad
CHOLINGA CHOPHATIKIZANA	21.2 ± 1dB
MTUNDU WOTSALIRA	Standard
MAPULOGALAMU	-

### Matanthauzo okhudzana

TDK Corporation HHM2910E1	AAAA Distributor	HHM2910E1 Wopereka
HHM2910E1 Mtengo	HHM2910E1 Zithunzi	HHM2910E1 Image
HHM2910E1 PDF Datasheet	HHM2910E1 Dinani Datasheet	HHM2910E1 Datasheet
HHM2910E1 Stock	Gulani HHM2910E1	Gulani TDK Corporation HHM2910E1
TDK Corporation HHM2910E1	TDK Corporation Wogulitsa	TDK Corporation Distributor
TDK Corporation HHM2910E1		

### Zogwirizana

<p><b>HHM2319B2</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 824-915MHZ 0805                  Zilipo: 561662 pcs  <a href="#">RFQ</a></p>	<p><b>HHM2909C4</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 777-925MHZ 0402                  Zilipo: 881596 pcs  <a href="#">RFQ</a></p>
<p><b>HHM2220SA3</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 1.92-1.98GHZ 0603                  Zilipo: 72297 pcs  <a href="#">RFQ</a></p>	<p><b>HHM2917B1</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 2.4-2.5GHZ 0402                  Zilipo: 348500 pcs  <a href="#">RFQ</a></p>
<p><b>HHM2915A2</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 0402                  Zilipo: 1013985 pcs  <a href="#">RFQ</a></p>	<p><b>HHM2510B1</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 2.4-2.5GHZ 0202                  Zilipo: 294482 pcs  <a href="#">RFQ</a></p>
<p><b>HHM2910E4</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 1.71GHZ-1.98GHZ                  Zilipo: 383268 pcs  <a href="#">RFQ</a></p>	<p><b>HHM2919A2</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 2.4-2.5GHZ 0402                  Zilipo: 880371 pcs  <a href="#">RFQ</a></p>
<p><b>HHM2933A1</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 2.4-2.5GHZ 0402                  Zilipo: 1018819 pcs  <a href="#">RFQ</a></p>	<p><b>HHM2293A1</b>                  Opanga: TDK Corporation                  Kufotokozera: MULTILAYER DIVIDER FOR W-LAN/BLU                  Zilipo: 909724 pcs  <a href="#">RFQ</a></p>
<p><b>HHM2215SA5</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 824-915MHZ 0603                  Zilipo: 75095 pcs  <a href="#">RFQ</a></p>	<p><b>HHM2942A2</b>                  Opanga: TDK Corporation                  Kufotokozera: RF DIR COUPLER 2.4-2.5GHZ 0402                  Zilipo: 1115188 pcs  <a href="#">RFQ</a></p>

