



TDK Corporation

HHM1603A1

Gawo la Nambala:

Wopanga / Chinthu:

Mafotokozedwe Akatundu

Datasheets:

Mkhalidwe wa RoHS

Zolembe

Chombo Chochokera

Njira Yopereker

HHM1603A1

TDK Corporation

BALUN 2.3GHZ-2.7GHZ 50/100 4SMD

[HHM1603A1.pdf](#)

Kutsogolera / RoHS Kumvera

120843 pcs stock

Hong Kong

DHL/Fedex/TNT/UPS/EMS

PEMPHO LA QUOTATION

Chithunzi chingakhale choyimira. Onani ndondomeko zogwiritsira ntchito mankhwala.

Mafofokozedwe a HHM1603A1

GAWO LA NAMBALA	HHM1603A1
WOPANGA	TDK Corporation
KUFOTOKOZERA	BALUN 2.3GHZ-2.7GHZ 50/100 4SMD
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Kutsogolera / RoHS Kumvera
CHIWERENGERO CHIPEZEKA	120843 pcs
TSAMBA LAZAMBIRI	HHM1603A1.pdf
MNDANDANDA	-
BWERERANI KUTAYIKA (MIN)	10dB
KUSIYANA KWA PHASE	180° ±10°
KUPAKA	Cut Tape (CT)
PHUKUSI / MLANDUWU	4-SMD
MAINA ENA	445-173060-1
MTUNDU WOKWERA	Surface Mount
MPHUNO YOPANDA CHISOKONEZO (MSL)	1 (Unlimited)
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Lead free / RoHS Compliant
KUTAYA KULOWA (MAX)	0.5dB
KUTAYA MTIMA - KUSAYENERERA / KUSAMALA	50 / 100 Ohm
CHIWERENGERO CHAFUPIPAFUPI	2.3GHz ~ 2.7GHz
KUFOTOKOZEDWA KWAMBIRI	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 4-SMD

Matanthauzo okhudzana

TDK Corporation HHM1603A1	AAAA Distributor	HHM1603A1 Wopereka
HHM1603A1 Mtengo	HHM1603A1 Zithunzi	HHM1603A1 Image
HHM1603A1 PDF Datasheet	HHM1603A1 Dinani Datasheet	HHM1603A1 Datasheet
HHM1603A1 Stock	Gulani HHM1603A1	Gulani TDK Corporation HHM1603A1
TDK Corporation HHM1603A1	TDK Corporation Wogulitsa	TDK Corporation Distributor
TDK Corporation HHM1603A1		

Zogwirizana

<p>HHM1591D1 Opanga: TDK Corporation Kufotokozera: BALUN 350MHZ-470MHZ 50/100 0805 Zilipo: 466597 pcs</p> <p>RFQ</p>	<p>HHM1596A1 Opanga: TDK Corporation Kufotokozera: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Zilipo: 493437 pcs</p> <p>RFQ</p>
<p>HHM1589B1 Opanga: TDK Corporation Kufotokozera: BALUN 470MHZ-710MHZ 6SMD Zilipo: 234016 pcs</p> <p>RFQ</p>	<p>HHM17139B1 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Zilipo: 255709 pcs</p> <p>RFQ</p>
<p>HHM1583B1 Opanga: TDK Corporation Kufotokozera: BALUN 3.1GHZ-4.9GHZ 50/100 0805 Zilipo: 404898 pcs</p> <p>RFQ</p>	<p>HHM1595A1 Opanga: TDK Corporation Kufotokozera: BALUN 3GHZ-8GHZ 50/100 0805 Zilipo: 163352 pcs</p> <p>RFQ</p>
<p>HHM1711D1 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Zilipo: 180690 pcs</p> <p>RFQ</p>	<p>HHM1710D1 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Zilipo: 460907 pcs</p> <p>RFQ</p>
<p>HHM17125D1 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Zilipo: 496156 pcs</p> <p>RFQ</p>	<p>HHM1589E1 Opanga: TDK Corporation Kufotokozera: BALUN 350MHZ-470MHZ 50/200 0805 Zilipo: 435579 pcs</p> <p>RFQ</p>
<p>HHM1711Q1 Opanga: TDK Corporation Kufotokozera: BALUN 2.3GHZ-3.8GHZ 50/100 0603 Zilipo: 836875 pcs</p> <p>RFQ</p>	<p>HHM1711E1 Opanga: TDK Corporation Kufotokozera: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Zilipo: 796296 pcs</p> <p>RFQ</p>