



AVX Corporation

CP0805A1880BWTR

Gawo la Nambala:

CP0805A1880BWTR

Wopanga / Chinthu:

AVX Corporation

Mafotokozedwe Akatundu

RF DIR COUPLER 1.85-1.91GHZ 0805

Datasheets:

CP0805A1880BWTR.pdf

Mkhalidwe wa RoHS

Ili ndi kutsogolera / RoHS yosagwirizana

Zolembe

282423 pcs stock

Chombo Chochokera

Hong Kong

Njira Yopereker

DHL/Fedex/TNT/UPS/EMS

PEMPHO LA QUOTATION

Chithunzi chingakhale choyimira. Onani ndondomeko zogwiritsira ntchito mankhwala.

Mafotokozedwe a CP0805A1880BWTR

GAWO LA NAMBALA	CP0805A1880BWTR
WOPANGA	AVX Corporation
KUFOTOKOZERA	RF DIR COUPLER 1.85-1.91GHZ 0805
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Ili ndi kutsogolera / RoHS yosagwirizana
CHIWERENGERO CHIPEZEKA	282423 pcs
TSAMBA LAZAMBIRI	CP0805A1880BWTR.pdf
PHUKUSI LA CHIPANGIZO CHOTHANDIZIRA	0805
MNDANDANDA	-
BWERERANI KUTAYIKA	-29dB
MPHAMVU - MAX	3W
KUPAKA	Tape & Reel (TR)
PHUKUSI / MLANDUWU	0805 (2012 Metric)
MPHUNO YOPANDA CHISOKONEZO (MSL)	1 (Unlimited)
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Contains lead / RoHS non-compliant
KUSUNGULUMWA	-22dB
KULOWETSA KULOWA	0.6dB
KUSINTHASINTHA	1.85GHz ~ 1.91GHz
KUFOTOKOZEDWA KWAMBIRI	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 12 ± 1dB 3W 0805 (2012 Metric)
CHOLINGA CHOPHATIKIZANA	12 ± 1dB
MTUNDU WOTSALIRA	Standard
MAPULOGALAMU	PCS

Matanthauzo okhudzana

AVX Corporation CP0805A1880BWTR	AAAA Distributor	CP0805A1880BWTR Wopereka
CP0805A1880BWTR Mtengo	CP0805A1880BWTR Zithunzi	CP0805A1880BWTR Image
CP0805A1880BWTR PDF Datasheet	CP0805A1880BWTR Dinani Datasheet	CP0805A1880BWTR Datasheet
CP0805A1880BWTR Stock	Gulani CP0805A1880BWTR	Gulani AVX Corporation CP0805A1880BWTR
AVX Corporation CP0805A1880BWTR	AVX Corporation Wogulitsa	AVX Corporation Distributor
AVX Corporation CP0805A1880BWTR	AVX Corporation [MIL] CP0805A1880BWTR	

Zogwirizana

<p>CP0805A1907AWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLR 1.895-1.92GHZ 0805 Zilipo: 234814 pcs</p> <p>RFQ</p>	<p>CP0805A1842AWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLR 1.805-1.88GHZ 0805 Zilipo: 291374 pcs</p> <p>RFQ</p>
<p>CP0805A1960AWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.93-1.99GHZ 0805 Zilipo: 199692 pcs</p> <p>RFQ</p>	<p>CP0805A1747DWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLR 1.71-1.785GHZ 0805 Zilipo: 290903 pcs</p> <p>RFQ</p>
<p>CP0805A1890BWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.88-1.9GHZ 0805 Zilipo: 276537 pcs</p> <p>RFQ</p>	<p>CP0805A1890BWTR\500 Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.88-1.9GHZ 0805 Zilipo: 251680 pcs</p> <p>RFQ</p>
<p>CP0805A1880CWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.85-1.91GHZ 0805 Zilipo: 261094 pcs</p> <p>RFQ</p>	<p>CP0805A1747AWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLR 1.71-1.785GHZ 0805 Zilipo: 282291 pcs</p> <p>RFQ</p>
<p>CP0805A1747CWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLR 1.71-1.785GHZ 0805 Zilipo: 299089 pcs</p> <p>RFQ</p>	<p>CP0805A1720BWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.72GHZ 0805 Zilipo: 257960 pcs</p> <p>RFQ</p>
<p>CP0805A1880EWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.85-1.91GHZ 0805 Zilipo: 279177 pcs</p> <p>RFQ</p>	<p>CP0805A1880AWTR Opanga: AVX Corporation Kufotokozera: RF DIR COUPLER 1.85-1.91GHZ 0805 Zilipo: 309114 pcs</p> <p>RFQ</p>

